



# SERVICE BULLETIN

from: TRIO-KENWOOD COMMUNICATIONS, INC.

46

SUBJECT: TS-520/520S CW FREQUENCY SHIFT

DATE 8/6/79

Reports of intermittent frequency shift during CW operation, on the order of a few hundred cycles, may be traced directly to the Carrier unit.

On the Carrier unit X50-0009-01, install a ground lead of #18 tinned wire or similar, between the cases of T1 transformer and X3, the LSB XTAL. Recheck frequencies after installing this ground lead.

Please notate your Service Manuals.

JEB/yn

