

## Communications Division Service Bulletin

# ATB-0029

Date: April 14, 2004

### Title: TM-D700A CROSS BAND REPEAT AUDIO QUALITY IMPROVEMENT

At Serial Number 511xxxxx, a production change was made to improve cross band repeat audio quality. The value of C821 and R828 on the TX-RX (Control) PCB were changed.

	Original Value	Original P/N	New Value	New P/N
C821	0.1uF	CK73GB1C104K	6800pF	CK73GB1H682K
R828	10K	RK73GB1J103J	8.2K	RK73GB1J822J

The two components are at address location N11 of the foil side view of the TX-RX (Control) PCB on pages 55 and 56 of the Service Manual.

The two components are at address location AH5 of the TX-RX (Control) schematic.

**The content of this bulletin is for information only. The improvement is not covered under warranty.**