

ENGINEERING CHANGE NOTICE

| | |
|---|--|
| <p>PROBLEM DESCRIPTION (be specific) Limited control of AMC. Changing R-249 to 47K provides full control of AMC circuit.</p> | <p>Date: APRIL 10 09 ECN No. G100409 Requested by: RFL Engr Approval: RF Ltd Approval Service Approval Mfg Approval Field Retrofit? YES MOD LEVEL CHANGE?</p> |
|---|--|

| APPLICABILITY | S3-50 | S6-50 | S9-50 | S3-80 | S6-80 | S9-80 | OTHER |
|--|-------|-------|-------|-------|-------|-------|-------|
| List Serial Numbers Affected (if known) | | | | | | | |
| All "S" series radios using 0169 main boards | Y | Y | Y | Y | Y | Y | |

| SOLUTION |
|---------------------------------------|
| Change value of R-249 from 10K to 47K |